
Version 12/10/2023 Domat Visual 2.6.0.1, Web application 2.0.2

- Application Rebrand
- Fixed: an occasional issue with connecting to the Proxy.

Version 04/07/2023 Merbon Visual 2.5.0.7, Web application 2.0.2

- Fixed: write in time schedules
- Fixed: display of the master alarm

Version 21/03/2023 Merbon Visual 2.5.0.5, Web application 2.0.2

- Added support for new HMI objects (Slider, Progress Bar, Pop-up, Alarm Point)
- Added an alarm log
- Added DNS support
- IP address display after HT200 start
- Possibility to disable the web interface in "Settings"
- Conversion of the "Communication timeout" item from ms to s
- Fixed: Display of default value for binary functions
- Fixed: "Display Calibration" option
- Fixed: The loading of the HT200 application when the progress bar did not correspond to reality
- Fixed: Bug where the Czech localization changed to English after uploading the definition
- Fixed: User policy for alarms and TPG
- Fixed: Name indentation for alarm detail
- Fixed: Display of the bar in the alarm log
- Fixed: Alarm log display according to user rights
- Fixed: Alarm log loading display
- Fixed: Text scrolling in the alarm log
- Fixed: Gap between the "Restore" and "Close" buttons in the alarm log
- Fixed: Slider color of the Slider object
- Fixed: The time setting, when it was possible to make a change only after changing the month
- Fixed: Bug where after clicking from a graphic to a text template (SoftPLC) the template was deleted

Version 22/02/2021 Merbon Visual 2.4.0.14, Web application 2.0.2

- Text changed from „Menu“ to „Configuration“ at "Menu -> Definition -> Configuration".
- Improved closing of the „About“ dialogue.
- Fixed: Frozen terminal when keyboard displayed
- Demo project with graphical definition added
- Display backlight increasing gradually rather than on/off
- Inclusion of a patch that resolves the touch panel disconnection

Version 01/10/2020 PATCH for Merbon Visual 2.4.0.11, Web Application ver. 2.0.2

- Fixed: Spontaneous disconnection of the touch panel, cases when the green LED was lit and the terminal could not wake up from power saving mode.

Version 05/06/2020 Merbon Visual 2.4.0.11, Web application 2.0.2

- Fixed: Master alarm click through
 - Fixed: word/dword/lword/byte datatypes writing
 - Fixed: Display of buttons at objects Digital Setter, Digital Indicator, Digital Setter ComboBox and Digital Setter Buttons
 - Fixed: Text string display at objects Text Setter and Value Indicator
 - Fixed: Terminal freezing when String datatype used
-

Version 18/12/2019 Merbon Visual 2.4.0.7, Web application 2.0.2

- Merbon Visual – new version of application:
 - Add Portuguese and German localization
 - Fixed reversal of logical states in BOOL time program
 - Add Text setter, Value indicator, and Digital Setter Buttons objects
-

Version 26/04/2018 Merbon Visual 2.3.0.8, Web application 2.0.2

- Merbon Visual – new version of application:
 - Fix of minor bugs
 - New control of user rights on button to access other pages
-

Version 14/12/2017 Merbon Visual 2.3.0.3, Web application 2.0.2

- Merbon Visual – new version of application
 - New graphic menu definition for mark... controllers (only for controllers for Merbon IDE)
 - Option to upload definition files from Merbon IDE by SSCP protocol on port 12346
-

Version 29/08/2016 Merbon Menu Reader 1.01 RC4, Web application 1.0.0.6

- Merbon Menu Reader – For SoftPLC link is set variable quality in PLC as good instead of manual.
-

Version 09/08/2016 Merbon Menu Reader 1.01 RC3, Web application 1.0.0.6

- Merbon Menu Reader – Fixed displaying special symbol nearby °C.
 - Web application – Deleted free space in language selection.
-

Version 26/07/2016 Merbon Menu Reader 1.01, Web application 1.0.0.5

- Merbon Menu Reader – Fixed displaying of analog setter range.
-

Version 01/07/2016 Merbon Menu Reader 1.00 RC14, Web application 1.0.0.5

- First version.