

Release notes:

Devices with the following serial numbers may show a problem with device freeze because of new parallel NOR flash memory:

147994, 147995, 147996, 147997, 147998, 147999, 148000, 148001, 148002, 148448, 148449, 148955, 148956, 148957, 148958, 148959, 149061, 149062, 149063, 149064, 149378, 149383, 149385, 149387, 152931, 152932, 152933, 152934, 152935, 154004, 154005, 154006, 154007, 154008, 155685, 155686, 155687, 155688, 155689, 157092, 157093, 157094, 157095, 157096

In case of freezing, there only will be network settings on the LCD display, and the device does not load the customized menu. Please contact technical support, support@domat.cz

v104 Version released 16. 1. 2019

- Readout of system time after start
- Fix of range at Analog setter
- Fix of exceptions in time schedulers, exceptions now start from 1.1.2019
- Maximum array range fixed for time scheduler editor
- Fix of range at real time scheduler
- Exception in time schedulers with end date/time preceding the start date/time will not be saved
- Automatic terminal restart after text definition upload
- Fixes for new parallel NOR flash memory
- Layout of flash memory changed
- Fix of FS
- Fix of FW update over POST
- Fix of copying of new FW in bootloader

v103 Version released 10. 12. 2015

- Fix of DHCP at text definition upload
- Introducing of TimeOut for IP address from DHCP for display at the LCD
- Implementation of "time limited switch"
- Fix of TPG editor